

## Homecheck Environmental



### Contamination Risk **PASSED**

#### Professional Opinion

Argyll Environmental Consultants have passed this report in accordance with the definition of contaminated land within Part 2A of the Environmental Protection Act 1990. Please refer to the Professional Opinion page and Section 1 for further information.

Report issued for the property at

**Sample Site  
Sample Town**

Report Reference  
**235702860\_1\_1**

National Grid Reference  
**491040 106950**

Customer Reference  
**Sample Site\_HCP**

Report Date  
**24 February 2020**



### Flood Risk: None Identified

Refer to Section 2 for further information

#### Conveyancer Guidance

While this report may have identified areas at risk of flooding within 250m of the search centre, we consider there to be no significant risk of flooding to the property. Please refer to Section 2 for further information.

#### Contact Details

If you require assistance please contact your Search Provider or phone Customer Services on 0844 844 9966 or email [helpdesk@homecheck.co.uk](mailto:helpdesk@homecheck.co.uk)



### Radon: IDENTIFIED

Refer to Section 3 for further information

#### Landmark Contribution

By purchasing this report, the recipient may be eligible for Remediation Contribution of up to £100,000 if served with a Remediation Notice by the Local Authority. Such a notice may require the homeowner to pay for all, or contribute to, the remediation of the property. For more information see Landmark's Terms and Conditions.



### Ground Stability: IDENTIFIED

Refer to Section 4 for further information



### Other Influential Factors:

Refer to Section 5 for further information

**Environmental Constraints: None Identified**

**See Section 5a**



## Professional Opinion

Contamination Risk

# PASSED

In the professional opinion of Argyll Environmental Consultants, the level of contamination risk associated with the information disclosed in the Homecheck Professional report dated 24th February 2020 and reference 235702860\_1\_1, Sample Site\_HCP for

**Sample Site**  
**Sample Town**

1) is unlikely that the property would be designated "contaminated land" within the meaning of Part 2A of the Environmental Protection Act 1990.

2) is unlikely to have an adverse effect on the security of the property for normal lending purposes.

The professional opinion refers to Section 1 of this report and should always be read in conjunction with the full text of that report. No physical site inspection or survey has been carried out or is proposed.

Approved by

**Argyll Environmental Ltd**

